
SERVICE BULLETIN

Original Issue Date: **8/90**
Model: **125-180ROZJ (John Deere 6076TF/6076AF engines)**
Market: **Industrial**
Subject: **Valve Clearance Service Interval**

This following information is furnished as a reminder.

The engine valve clearance service interval, as recommended by the engine manufacturer, varies by engine serial number.

Starting with engine serial no. 6076TF121170 or 6076AF121170, perform valve clearance adjustment at every 1200 hours.

Prior to engine serial no. 6076TF121170 or 6076AF121170, perform valve clearance adjustment at 100 hours (break-in period) and every 1200 hours.

Failure to perform the valve clearance adjustment at the recommended intervals causes deteriorated performance and can cause major internal engine damage to the solid-lifter engine.

Complete maintenance information is found in the Engine Operator's Manual TP-5361 along with the valve clearance adjustment procedure.

When doing the next required routine maintenance, check the service log and verify that the engine valve clearance adjustment was made.

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							