


PARTS BULLETIN

Original Issue Date: **4/95**
 Model: **8C, 10C, 12C**
 Market: **Marine**
 Subject: **End Bracket Bearing Change**

Kohler Co. has introduced a design change to improve end bracket and bearing life. New end brackets are identified by 1) a notched bearing which requires a pin and 2) a letter "P" stamped on the outside of the end bracket.

See Figure 1 for location. The end bracket and bearing are sold separately. Choose the correct bearing from the following table. This change will be reflected in parts catalogs as they are updated.

Generator End Bracket	Part Number	
	Bearing	New End Bracket
Stamped with the letter "P"	X-758-17	344128
Not Stamped with the letter "P"	X-758-1	-



299138-

1. Approximate location of metal punch stamp

Figure 1. End Bracket

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							