

PARTS BULLETIN

Original Issue Date: 3/02
Models: 30-60 kW with General Motors 4.3 L and 5.7 L Engines
Market: Industrial
Subject: Throttle Valve Service Kits GM23538 and GM23539

Throttle valve part number GM16169 used on 30-60 kW generator sets has been replaced by service kit GM23538 on the 4.3L engine (Figure 1) and service kit GM23539 on the 5.7L engine (Figure 2).

Components of the service kits are shown below and on the following page.




Figure 1 Kit GM23538 for 4.3 L Engine

(continued)

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							



1. GM16150 Gasket, carburetor
2. GM23540 Valve, PF42 w/o PH (gov)
3. GM23541 Spacer, U-bolt plate
4. GM16175 Adapter, manifold
5. GM16202 Gasket, intake manifold

PB90_2

Figure 2 Kit GM23539 for 5.7 L Engine