

PARTS BULLETIN

Original Issue Date: 6/02
Models: 8-22 kW with Ford VSG-413 Engine
Market: Residential/Commercial, Marine, and Mobile Generator Sets
Subject: Ignition Coil and Spark Plug Wires

Ford Power Products installed a new ignition coil and spark plug wires on VSG-413 engines to improve ignition coil performance and durability. The change took place with approximately August/September 1998 engine production.

When replacing the ignition coil and spark plug wires, **use the Build Date on the engine's nameplate** and the illustrations below to determine if this bulletin is applicable to your unit. For units with build date later than August/September 1998, refer to Figure 1 to

identify replacement parts. Refer to the generator set parts catalog for part numbers if your unit's engine was built before August/September 1998.

The following parts catalogs will reflect the change as they are updated:

Parts Catalog Number	Description
TP-5411	P/C 10/12CC/CZ/CCE/CEZ
TP-5413	P/C 8/10/12.5C/E
TP-5849	P/C 10RY/RZ, 12RY/RZ
TP-6007	P/C 17/22RY




Figure 1 Ford VSG-413 Ignition Coil and Spark Plug Wires