

# Service Bulletins

Sorted by Part Number

Description	Part No.	Rev.
Stator Alignment, 4.5RV	<a href="#">SB-480</a>	8/88
Controller Replacement, 3.7-7CM RV	<a href="#">SB-495</a>	2/90
Fuel Leaks, 2.5CM/Z LP	<a href="#">SB-500</a>	7/90
Stator Leads, PowerBoost III	<a href="#">SB-501</a>	8/90
Muffler Kit PA-278317	<a href="#">SB-508</a>	12/90
Warranty 5CMZ	<a href="#">SB-511</a>	2/91
Reconnection 4-Lead, Single-Phase	<a href="#">SB-512</a>	2/91
Remote Panel Wiring	<a href="#">SB-516</a>	6/91
Choke Adjustment	<a href="#">SB-520</a>	2/92
Timing Mark, 7CCO-RV	<a href="#">SB-525</a>	3/94
Diesel Fuel High Sulfur	<a href="#">SB-532</a>	11/94
Regulator Relocation 4/5/7CCKM RV	<a href="#">SB-533</a>	2/96
Electronic Governor Control	<a href="#">SB-555</a>	5/96
PowerBoost V Voltage Regulator	<a href="#">SB-559</a>	10/96
Engine Coolant/Antifreeze	<a href="#">SB-567</a>	12/96
Engine Fan Bolt, 10-12RY/RZ CC/CZ	<a href="#">SB-571</a>	7/97

