

# RV/Mobile Generator Set Manuals

<b>Parts Catalogs</b>		
<b>Description</b>	<b>Part No.</b>	<b>Rev.</b>
PARTS CATALOG INDEX	<a href="#">TP-5366</a>	2/97a
7.5A/C/R Kohler L654	<a href="#">TP-5045</a>	8/98
4.5CKM Kohler KT17	<a href="#">TP-5060</a>	3/86
12.5 kW Perkins 4.108	<a href="#">TP-5101</a>	9/84
2/2.5CM/CMZ Tecumseh TVM 140	<a href="#">TP-5143</a>	8/91
4.5CKM Kohler KT17	<a href="#">TP-5146</a>	6/93
9/12.5/14CCO Yanmar	<a href="#">TP-5228</a>	10/93
7CMZ Kohler K582	<a href="#">TP-5253</a>	7/89
7CKM Kohler K582	<a href="#">TP-5349</a>	3/92
4/5CKM Kohler M18/20	<a href="#">TP-5395</a>	4/97a
10/12CC/CZ Ford VSG411/413	<a href="#">TP-5411</a>	6/98
7CCKM/CCKMR Kohler K582	<a href="#">TP-5577</a>	5/95b
7/10CCO/CCOZ Kubota V-905/V-1305	<a href="#">TP-5596</a>	1/97a
15/20CCO/CCFO Yanmar 4TN	<a href="#">TP-5607</a>	10/97
7ER/6EFR	<a href="#">TP-6036</a>	6/99

<b>Parts Bulletins</b>		
<b>Description</b>	<b>Part No.</b>	<b>Rev.</b>
Carburetor, Tillotson L600 Engine	<a href="#">PB-07</a>	1/76
Diesel Fuel Solenoids	<a href="#">PB-32</a>	3/91
Relay A-233059 Replacement	<a href="#">PB-37</a>	11/93
Cntrl Replace 3.5/4.5/5.5/7CM	<a href="#">PB-39</a>	9/92
4/5/7 kW Circuit Breaker Replacement	<a href="#">PB-40</a>	11/92
Relays 233180 and A-243997	<a href="#">PB-42</a>	3/94
Thermostat Cover Change 10/12 kW	<a href="#">PB-45</a>	5/94
Oil Pressure Switch	<a href="#">PB-49</a>	1/95
Regulator Relocation	<a href="#">PB-65</a>	12/95
Glow Plug RV	<a href="#">PB-67</a>	4/96

