

**PARTS BULLETIN**

Original Issue Date: **10/04**

Models: **200-400REOZV with Weather Enclosure**

Market: **Industrial**

Subject: **Service Kits for GM25836-KA1, GM25836-KA3, GM25836-KA4, and GM25858-KA1**

Several parts used in the weather enclosure kits were discontinued effective March 8, 2004. Use the Replacement Selection Table below to determine the service kit required to replace discontinued parts on your weather enclosure kit.

When using KOHLERnet to determine housing bill of materials, use the generator set *build date* as the *BOM Valid From Date*. If you use the default current date as the *BOM Valid From Date*, the parts used on units built today will be displayed, and the new parts are not a direct replacement for the discontinued parts.

**Replacement Selection Table**

Discontinued Part	Description	Weather Enclosure Kit	Housing Shroud Replacement Service Kit
GM25841	Support, housing front (RS)	GM25836-KA1/KP1	GM34421
GM25842	Support, housing front (LS)		
GM25843	Support, housing front (RS)	GM25836-KA3/KP3	GM34419
		GM25858-KA1/KP1	
		GM25836-KA4/KP4	GM34420
GM25844	Support, housing front (LS)	GM25836-KA3/KP3	GM34419
		GM25858-KA1/KP1	
		GM25836-KA4/KP4	GM34420
GM25848	Panel, housing front	GM25836-KA1/KP1	GM34421
		GM25836-KA3/KP3	GM34419
		GM25836-KA4/KP4	GM34420
		GM25858-KA1/KP1	GM34419

**Service Kit Content**

Description	Qty.	Part Number in Service Kit		
		GM34419	GM34420	GM34421
Support, housing front (RS)	1	GM33826	GM33826	GM33824
Support, housing front (LS)	1	GM33827	GM33827	GM33825
Panel, top housing front	1	GM33810	GM33810	GM33810
Panel, bottom housing front	1	GM33811	GM33811	GM33811
Frame, air duct (vertical)	2	GM23645	GM33806	GM33806
Frame, air duct (horizontal)	2	GM23646	GM33807	GM33807
Rivet, pop .187 in.	8	X-781-11	X-781-11	X-781-11
Screw, hex cap	12	M933-08020-60	M933-08020-60	M933-08020-60
Washer, plain	12	M125A-08-80	M125A-08-80	M125A-08-80