

KOHLER[®] POWER SYSTEMS

PARTS BULLETIN

ISSUE DATE: **9/92** MODEL: **3.5/4.5CM, and** SUBJECT: **Controller** NO.: **39**
 REVISION DATE: - **5.5/7CM-RV** **Replacement**

Due to the increasing tooling cost of manufacturing the C-269156 Controller Box and the 241807 Controller Cover, these parts will no longer be supplied in Controller Replacement Kits 228552, 228553, 228554, and 228655. Each of these kits will require saving the old cover and box and replacing the inside components and wiring harness when necessary.

Model No.	3.5CM	4.5CM	5.5/7CM	7CM
Kit No.	228552	228554	228553	228655
Controller Assembly	A-241994	A-241994	A-241994	A-241993
Interlock Relay Assembly	A-238755	A-277821	A-241760	N/A
Instruction Sheet	TT-721	TT-721	TT-721	TT-721

The kits will include complete installation instructions.

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							

